



A

B

PHOTOGRAPH A & B indicating sections of pre-cast concrete revetment units having collapsed, with deterioration of sheet piling and cast in-situ concrete along bottom section of pier.



AERIAL PHOTOGRAPH INDICATING LOCATION OF WORKS